



Robinson Helicopter Parts

3948 Aviation Cir. NW, Atlanta, Georgia 30336

Phone 404.424.9105 Fax 404.601.9795



2016 Rotorcorp Lycoming Engine Pricing

Rotorcorp is pleased to offer a full complement of factory Lycoming engines and field overhauled engines for your Robinson R44 or R22 Helicopter. Robinson helicopter operators and maintenance facilities around the world can now take advantage the best pricing for factory new/outright or exchange engines with our turn-key global shipping and core return program. Rotorcorp can even coordinate your engine with the appropriate Robinson build-up kit for seamless installation. Call today for specials and discounts.

R22 Beta: Lycoming O-320-B2C Engines

Overhaul Exchange (HENPL-RT8864)*	\$28,059
Rebuilt Exchange (RENPL-RT8864)*	\$32,937
New Exchange (ENPL-RT8864)*	\$53,540
New Outright (ENPL-RT8864).....	\$64,248
Field Overhaul (Roller Lifter Add \$2600).....	\$17,830
Engine Buildup Kit (R8299).....	\$2,600

*Exchange engines require either a \$16,000 core deposit with order or submittal of core engine in advance of order to waive core deposit. Prices do not include freight and shipping charges. Prices subject to change without notice.

R22 Beta II: Lycoming O-360-J2A Engines

Overhaul Exchange (HENPL-RT10200)*	\$28,290
Rebuilt Exchange (RENPL-RT10200)*	\$33,168
New Exchange (ENPL- RT10200)*	\$53,273
New Outright (ENPL- RT10200).....	\$63,927
Field Overhaul (Roller Lifter Add \$2600).....	\$17,900
Engine Buildup Kit (R8300).....	\$2,600

*Exchange engines require either a \$16,400 core deposit with order or submittal of core engine in advance of order to waive core deposit. Prices do not include freight and shipping charges. Prices subject to change without notice.

R44 Astro & Raven I: Lycoming O-540-F1B5 Engines

Overhaul Exchange (HENPL-RT10292)*	\$39,424
Rebuilt Exchange (RENPL- RT10292)*	\$44,911
New Exchange (ENPL- RT10292)*	\$72,423
New Outright (ENPL- RT10292).....	\$86,907
Field Overhaul (Roller Lifter Add \$3200).....	\$24,900
Engine Buildup Kit (R8301).....	\$4,000

*Exchange engines require either a \$20,400 core deposit with order or submittal of core engine in advance of order to waive core deposit. Prices do not include freight and shipping charges. Prices subject to change without notice.

[Continued]



Robinson Helicopter Parts

3948 Aviation Cir. NW, Atlanta, Georgia 30336

Phone 404.424.9105 Fax 404.601.9795

R44 Raven II: Lycoming IO-540-AE1A5 Engines

Overhaul Exchange (HENPL-RT10356)*.....	\$55,881
Rebuilt Exchange (RENPL- RT10356)*	\$61,369
New Exchange (ENPL- RT10356)*	\$92,268
New Outright (ENPL- RT10356).....	\$110,721
Field Overhaul (Roller Lifter Add \$3200).....	\$35,000
Engine Buildup Kit (R8302).....	\$4,200

*Exchange engines require either a \$21,600 core deposit with order or submittal of core engine in advance of order to waive core deposit. Prices do not include freight and shipping charges. Prices subject to change without notice.

Don't Pay Your Engine Shop for a Crankshaft on your O-540 or IO-540 Engine!

Airworthiness Directive 2012-19-01 has been issued by the FAA in September 2012 for certain O-540 and IO-540 engines installed in Robinson R44 helicopters. RotorCorp has arranged for priority pricing on Lycoming factory overhauled and rebuilt zero time engines that renders this new AD a non-issue for R44helicopter owners around the world. The AD requires mandatory replacement of engine crankshaft at overhaul on those Lycoming engines specified in Lycoming Service Bulletin 569A and Supplement 569A. In most cases, crankshaft-subject engines can be submitted as cores with NO PENALTY! [Click For Details](#)

Call Rotorcorp today 404-424-9105 or visit us online!