



Robinson Helicopter Parts

3948 Aviation Cir. NW, Atlanta, Georgia 30336

Phone 404.424.9105 Fax 404.601.9795



2016 Rotorcorp Overhaul Kit Pricing: Robinson R44 RAVEN II

Thank you for contacting Rotorcorp for the approaching overhaul on your *Robinson R44 Raven II helicopter!* Complete field overhaul kits combine the overhaul/exchange components together with the new parts to perform the airframe overhaul in the field. The following kit package offers an easy and convenient way to order all necessary components at a discounted price.

R44 Raven II Field Component Overhaul Kit (R8210)..... \$137,000

Includes: main rotor and tail rotor blades, spindles, flex plates, fanwheel, belts, main & tail gearboxes, swashplate, clutch, actuator, fanshaft, pitch control, TR driveshaft and shoulder harness. See RHC Kit Contents (attached).

R44 Raven II Core Charge, Refundable (R8212).....\$39,945

Note: The core charge is forwarded by the Service Center to Robinson Helicopter Company and is refunded upon receipt and inspection of acceptable core components. The amount of the core charge refunded to the customer is typically 80-85% of the amount paid, as determined at the sole discretion of Robinson Helicopter Company. The service center typically receives the core fee refund within 6-8 weeks from the time the components are received by Robinson Helicopter Company.

IO-540 Engine Build-Up Kit (R8302)..... \$4,200

Includes all engine cooling panels, gaskets, hoses, lines, etc.

R44 Interior Overhaul Kit, Leather (R8014)..... \$6,800

R44 Interior Overhaul Kit, Velour (R8010)..... \$6,000

NOTE: Interior overhaul kit includes new seats, carpets, insulation, cyclic and collective boots, etc. *Must specify color* (blue, gray, brown, tan) *and heater location.*

Bladder Fuel Tanks (KI-196-2).....\$6,800

NOTE: Evidence of compliance with [SB-78B](#) is required if not ordering an overhaul kit with a bladder fuel tank. RHC requires an SO with matching aircraft s/n logbook entry. RHC \$1000 rebate extended until further notice. ([details](#))

Rotorcorp Engine Overhaul Exchange Program: Factory Direct Lycoming IO-540-AE1A5

We Offer Global Engine Shipping and Core Return!

Overhaul/Exchange(HENPL-RT10356).....	\$55,881 *
Rebuild/Exchange "Zero Time" (RENPL-RT10356).....	\$61,369 *
New/Exchange (ENPL-RT10356).....	\$92,268 *
New Outright (ENPL-RT10356)	\$110,721
Field Overhaul (Roller Lifter add \$3200).....	\$35,000

*\$21,600 refundable core deposit due on advance orders. OH Exchange engines are backed with a 1 year parts & labor factory warranty. Rebuilt "Zero Time" and New engines come with a full two year factory warranty on parts and labor.

[CONTINUED]



Robinson Helicopter Parts

3948 Aviation Cir. NW, Atlanta, Georgia 30336

Phone 404.424.9105 Fax 404.601.9795

NOTE: Airworthiness Directive 2012-19-01 has been issued by the FAA in September 2012 for certain O540 and IO-540 engines installed in Robinson R44 helicopters. RotorCorp has arranged for priority pricing on Lycoming factory overhauled and rebuilt zero time engines that renders this new AD a non-issue for R44helicopter owners around the world. The AD requires mandatory replacement of engine crankshaft at overhaul on those Lycoming engines specified in Lycoming Service Bulletin 569A and Supplement 569A.

[Click For Details](#)

We discount on overhaul kits. Discounts vary depending on the size of the total order submitted. The prices reflected above are 2016 retail prices valid through December, 31st 2016. We look forward to providing you with any additional information you may need to make an informed decision concerning your overhaul- please feel free to contact us for a formal estimate for your specific configuration and remember to ask about our complimentary tool loaner program with the purchase of any overhaul kit! Thanks in advance for your consideration!

Call Rotorcorp today 404-424-9105 or visit us online!