



Robinson Helicopter Parts

3948 Aviation Cir. NW, Atlanta, Georgia 30336

Phone 404.424.9105 Fax 404.601.9795



2021 Rotorcorp Overhaul Kit Pricing: Robinson R44 RAVEN II

Thank you for considering Rotorcorp for the approaching overhaul on your *Robinson R44 Raven II!* Overhaul kits contain overhauled/exchange and new parts to perform 2200 hour airframe maintenance and inspection in the field. Please refer to appropriate Illustrated Parts Catalog and Kit Instructions for kit contents. The following kit package offers an easy and convenient way to order all necessary components at a discounted price. Cost includes all crates for shipping.

R44 Raven II Field Component Overhaul Kit KI-4403 \$152,500

Includes: main rotor and tail rotor blades, spindles, flex plates, fanwheel, belts, main & tail gearboxes, swashplate, clutch, actuator, fanshaft, pitch control, TR driveshaft and shoulder harness. See RHC Kit Contents (attached). [R44 II \(Raven II & Clipper II\) 2200-Hour Inspection Kit Contents & Instructions.](#)

R44 Raven II Core Charge, Refundable (R8212).....\$39,060

Note: The core charge is forwarded by the Service Center to Robinson Helicopter Company and is refunded upon receipt and inspection of acceptable core components. The amount of the core charge refunded to the customer is typically 80-85% of the amount paid, as determined at the sole discretion of Robinson Helicopter Company. The service center typically receives the core fee refund within 6-8 weeks from the time the components are received by Robinson Helicopter Company.

IO-540 Engine Build-Up Kit KI-4406 \$4,900

R44 Interior Overhaul Kit, Leather KI-4407-2 \$8,400

R44 Interior Overhaul Kit, Velour KI-4407-1 \$7,600

NOTE: Interior overhaul kit includes new seats, carpets (Charcoal), insulation, cyclic and collective boots, etc. *Must specify color (gray or tan) and heater location.*

Bladder Fuel Tanks (KI-196-2).....\$11,800

NOTE: Evidence of compliance with SB-78B is required if not ordering an overhaul kit with a bladder fuel tank. RHC requires an SO with matching aircraft s/n logbook entry. RHC \$1000 rebate extended until further notice.

Lycoming Factory and Robinson Factory Exchange

IO-540-AE1A5 Engines

Lycoming Factory Overhaul Exchange (HENPL-RT10586)* \$57,457

Lycoming Factory Rebuilt Exchange (RENPL- RT10586)* \$63,555

Lycoming Factory New Exchange (ENPL- RT10586)* \$120,222

Lycoming Factory New Outright (ENPL- RT10586)..... \$141,822

Direct Field Overhaul (Your Engine)..... \$49,200

*Exchange engines require either a \$21,600 core deposit with order or submittal of core engine in advance of order to waive core deposit. Note: Per Lycoming SL-277, as of Jan. 6, 2020 Lycoming factory engines will no longer include an Alternator or Starter. ** Engine includes starter, alternator and is "built up" with KI-4405. Prices do not include freight and shipping charges. Prices are subject to change without notice.