



Robinson Helicopter Parts

3948 Aviation Cir. NW, Atlanta, Georgia 30336

Phone 404.424.9105 Fax 404.601.9795



### 2022 (Q3) Rotorcorp Lycoming Engine Pricing

Rotorcorp is pleased to offer a full complement of factory Lycoming engines and field overhauled engines for your Robinson R22 or R44 Helicopter. Robinson helicopter operators and maintenance facilities around the world can now take advantage the best pricing for factory new/outright or exchange engines with our turn-key global shipping and core return program. Rotorcorp can even coordinate your engine with the appropriate Robinson buildup kit for seamless installation. Call today for specials and discounts!

### **R22 Beta: Lycoming O-320-B2C Engines**

<b>Lycoming Factory Overhaul Exchange (HENPL-9715)*</b> .....	<b>\$45,583</b>
<b>Lycoming Factory Rebuilt Exchange (RENPL-9715)*</b> .....	<b>\$52,656</b>
<b>Lycoming Factory New Exchange (ENPL-9715)*</b> .....	<b>\$83,021</b>
<b>Lycoming Factory New Outright (ENPL-9715)</b> .....	<b>\$92,871</b>
<b>Field Direct Overhauled (Your Engine)</b> .....	<b>\$100,621</b>
<b>Engine Build-Up Kit KI-2204</b> .....	<b>\$3,000</b>

\*Lycoming Factory exchange O-320 engines require either a \$17,600 core deposit with order or submittal of a core engine in advance of the order to waive core deposit. Note: Per Lycoming SL-277, as of Jan. 6, 2020 Lycoming factory engines will no longer include an Alternator or Starter. \*\* Prices do not include freight and shipping charges. Prices are subject to change without notice.

### **R22 Beta II: Lycoming O-360-J2A Engines**

<b>Lycoming Factory Overhaul Exchange (HENPL- RT10603)*</b> .....	<b>\$ 40,653</b>
<b>Lycoming Factory Rebuilt Exchange (RENPL- RT10603)*</b> .....	<b>\$45,996</b>
<b>Lycoming Factory New Exchange (ENPL-RT10603)*</b> .....	<b>\$82,609</b>
<b>Lycoming Factory New Outright (ENPL- RT10603)</b> .....	<b>\$100,709</b>
<b>Field Direct Overhauled (Your Engine)</b> .....	<b>\$23,350</b>
<b>Engine Build-Up Kit KI-2205</b> .....	<b>\$3,400</b>

\*Lycoming Factory exchange engines require either a \$18,100 core deposit with order or submittal of core engine in advance of the order to waive core deposit. Note: Per Lycoming SL-277, as of Jan. 6, 2020 Lycoming factory engines will no longer include an Alternator or Starter \*\* Prices do not include freight and shipping charges. Prices are subject to change without notice.



Robinson Helicopter Parts

3948 Aviation Cir. NW, Atlanta, Georgia 30336

Phone 404.424.9105 Fax 404.601.9795

### R44 Raven I: Lycoming O-540-F1B5 Engines

Lycoming Factory Overhaul Exchange (HENPL-RT10877)* .....	\$57,740
Lycoming Factory Rebuilt Exchange (RENPL- RT10877)* .....	\$64,971
Lycoming Factory New Exchange (ENPL- RT10877)* .....	\$110,441
Lycoming Factory New Outright (ENPL- RT10877).....	\$132,941
Field Direct Overhaul (Your Engine) .....	\$33, 120
O-540 Engine Build-Up Kit KI-4405 .....	\$5,500

\*Exchange engines require either a \$22,500 core deposit with order or submittal of core engine in advance of order to waive core deposit. Note: Per Lycoming SL-277, as of Jan. 6, 2020 Lycoming factory engines will no longer include an Alternator or Starter \*\* Engine includes starter, alternator and is "built-up" with KI-4405. Prices do not include freight and shipping charges. Prices are subject to change without notice.

### R44 Raven II: Lycoming IO-540-AE1A5 Engines

Lycoming Factory Overhaul Exchange (HENPL-RT10586)* .....	\$69,592
Lycoming Factory Rebuilt Exchange (RENPL- RT10586)* .....	\$76,721
Lycoming Factory New Exchange (ENPL- RT10586)* .....	\$142,824
Lycoming Factory New Outright (ENPL- RT10586).....	\$166,624
Direct Field Overhaul (Your Engine).....	\$44,200
IO-540 Engine Build-Up Kit KI-4406 .....	\$5,500

\*Exchange engines require either a \$23,800 core deposit with order or submittal of core engine in advance of order to waive core deposit. Note: Per Lycoming SL-277, as of Jan. 6, 2020 Lycoming factory engines will no longer include an Alternator or Starter. \*\* Engine includes starter, alternator and is "built up" with KI-4405. Prices do not include freight and shipping charges. Prices are subject to change without notice.

**Call Rotorcorp today 404-424-9105 or visit us online!**