

3948 Aviation Cir. NW, Atlanta, Georgia 30336

Phone 404.424.9105 Fax 404.601.9795



2024 Rotorcorp Overhaul Kit Pricing: Robinson R44 Raven I

Thank you for considering Rotorcorp for the approaching 2200 hour overhaul on your *Robinson R44 Raven I Helicopter!* Overhaul kits contain overhauled/exchange and new parts to perform 2200 hour airframe maintenance and inspection in the field. Please refer to appropriate Illustrated Parts Catalog and Kit Instructions for detailed kit contents. The following kit package offers an easy and convenient way to order all necessary components at a discounted price. Cost includes all crates for shipping.

Rotorcorp Engine & Overhaul Kit Reservation Program

Current lead times for factory engines are expected to remain in the 2-year month range through 2024 and into 2025. Rotorcorp has arranged for the delivery of more than 60 engines in this period and we have made them available to our customers to reserve ahead of their anticipated delivery date. We can also coordinate the delivery of your 2200/2400 Hour Overhaul Kit in sync with your engine option.

View Program Details & Current Engine Positions

 R44 Interior Overhaul Kit, Leather KI-4407-2
 \$10,300

 R44 Interior Overhaul Kit, Velour KI-4407-1
 \$9,300

 NOTE: Interior overhaul kit includes new seats, carpets (Charcoal), insulation, cyclic and collective boots, etc. Must specify color (gray, charcoal or tan) and heater location.

(continued)



3948 Aviation Cir. NW, Atlanta, Georgia 30336

R44 Raven I/Cadet: Lycoming O-540-F1B5 Engines

Lycoming Factory Overhaul Exchange (HENPL-RT10877)*	\$ 61,256
Lycoming Factory Rebuilt Exchange (RENPL- RT10877)*	\$68,928
Lycoming Factory New Exchange (ENPL- RT10877)*	\$117,167

* Lycoming factory O-540 exchange engines \$28,200 core deposit with order <u>or</u> submittal of core engine in advance of order to waive core deposit. Note: Per Lycoming SL-277, as of Jan. 6, 2020 Lycoming factory engines will no longer include an Alternator or Starter. Prices are subject to change without notice.