



Robinson Helicopter Parts

3948 Aviation Cir. NW, Atlanta, Georgia 30336

Phone 404.424.9105 Fax 404.601.9795



2024 Rotorcorp Overhaul Kit Pricing: Robinson R44 RAVEN II

Thank you for considering Rotorcorp for the approaching 2200 hour overhaul on your *Robinson R44 Raven III*! Overhaul kits contain overhauled/exchange and new parts to perform 2200 hour airframe maintenance and inspection in the field. Please refer to appropriate Illustrated Parts Catalog and Kit Instructions for detailed kit contents. The following kit package offers an easy and convenient way to order all necessary components at a discounted price. Cost includes all crates for shipping.

Rotorcorp Engine & Overhaul Kit Reservation Program

Current lead times for factory engines are expected to remain in the 2-year month range through 2024 and into 2025. Rotorcorp has arranged for the delivery of more than 60 engines in this period and we have made them available to our customers to reserve ahead of their anticipated delivery date. We can also coordinate the delivery of your 2200/2400 Hour Overhaul Kit in sync with your engine option.

[View Program Details & Current Engine Positions](#)

R44 Raven II Field Component Overhaul Kit KI-4403 \$182,000
Includes: main rotor and tail rotor blades, spindles, flex plates, fanwheel, belts, main & tail gearboxes, swashplate, clutch, actuator, fan shaft, pitch control, TR driveshaft and shoulder harness. See RHC Kit Contents (Effective Aug 2020). [R44 II \(Raven II & Clipper II\) 2200-Hour Inspection Kit Contents & Instructions](#).

R44 Raven II Core Charge, Refundable (R8212).....\$42,060
Note: The core charge is forwarded by the Service Center to Robinson Helicopter Company and is refunded upon receipt and inspection of acceptable core components. The amount of the core charge refunded to the customer is typically 80-85% of the amount paid, as determined at the sole discretion of Robinson Helicopter Company. The service center typically receives the core fee refund within 6-8 weeks from the time the components are received by Robinson Helicopter Company.

IO-540 Engine Build-Up Kit KI-4406 \$6,300

R44 Interior Overhaul Kit, Leather KI-4407-2 \$10,300

R44 Interior Overhaul Kit, Velour KI-4407-1 \$9,300

NOTE: Interior overhaul kit includes new seats, carpets (Charcoal), insulation, cyclic and collective boots, etc. *Must specify color (gray or tan) and heater location.*

Bladder Fuel Tanks (KI-196-2).....\$13,400

NOTE: Evidence of compliance with SB-78B is required if not ordering an overhaul kit with a bladder fuel tank. RHC requires an SO with matching aircraft s/n logbook entry. RHC \$1000 rebate extended until further notice.

(Continued)



Robinson Helicopter Parts

3948 Aviation Cir. NW, Atlanta, Georgia 30336

Phone 404.424.9105 Fax 404.601.9795

R44 Raven II: Lycoming IO-540-AE1A5 Engines

Lycoming Factory Overhaul Exchange (HENPL-RT10586)*	\$73,798
Lycoming Factory Rebuilt Exchange (RENPL- RT10586)*	\$81,394
Lycoming Factory New Exchange (ENPL- RT10586)*	\$151,522

*Lycoming factory IO-540 exchange engines require either a \$29,500 core deposit with order or submittal of core engine in advance of order to waive core deposit. Note: Per Lycoming SL-277, as of Jan. 6, 2020 Lycoming factory engines will no longer include an Alternator or Starter.