



Robinson Helicopter Parts

3948 Aviation Cir. NW, Atlanta, Georgia 30336

Phone 404.424.9105 Fax 404.601.9795



2019 Rotorcorp Overhaul Kit Pricing: Robinson R22 BETA II

Thank you for contacting Rotorcorp for the approaching overhaul on your *Robinson R22 Beta II Helicopter!* Complete field overhaul kits combine the overhaul/exchange components together with the new parts to perform the airframe overhaul in the field. The following kit package offers an easy and convenient way to order all necessary components at a discounted price.

R22 Beta II Field Component Overhaul Kit KI-2203 (Supersedes R7951).....\$90,500*

Includes: Main rotor and tail rotor blades, spindles, flex plates, fanwheel, belts, main & tail gearboxes, swashplate, clutch, actuator, fanshaft, pitch control, TR driveshaft and shoulder harness. See Illustrated Parts Catalog pp 2.11-2.12 (attached) for full kit contents. **NOTE:** Includes KI-217-1 Bladder Tank Retrofit Kit, Per Service Bulletin 109 (Indicate white or primer). Deduct \$6400 if bladders previously installed.

R22 Beta II Core Charge, Refundable (R7952)..... \$16,200

Note: The core charge is forwarded by the Service Center to Robinson Helicopter Company and is refunded upon receipt and inspection of acceptable core components. The amount of the core charge refunded to the customer is typically 80-85% of the amount paid, as determined at the sole discretion of Robinson Helicopter Company. The service center typically receives the core fee refund within 6-8 weeks from the time the components are received by Robinson Helicopter Company.

O-360 Engine Build-Up Kit KI-2205 (Supersedes R8300)..... \$2,800

Includes all engine cooling panels, gaskets, hoses, lines, etc. (Specify A313-7 or -9 panel and ship S/N)

R22 Interior Overhaul Kit, Leather KI-2206-2 (Supersedes R8013)..... \$3,600

R22 Interior Overhaul Kit, Velour KI-2206-1 (Supersedes R8005)..... \$3,200

NOTE: Interior overhaul kit includes new seats, carpets, insulation, cyclic and collective boots, etc. *Must specify color (gray or tan) and heater location.*

**Rotorcorp Engine Overhaul Exchange Program: Factory Direct Lycoming O-360-J2A
We Offer Global Engine Shipping and Core Return!**

R22 Beta II: Lycoming O-360-J2A Engines

Overhaul Exchange (HENPL-RT10200)*	\$29,204
Rebuilt Exchange (RENPL-RT10200)*	\$34,692
New Exchange (ENPL- RT10200)*	\$58,912
New Outright (ENPL- RT10200).....	\$70,694

*Exchange engines require either a \$16,400 core deposit with order or submittal of core engine in advance of order to waive core deposit. Prices do not include freight and shipping charges. Prices subject to change without notice.

Call Rotorcorp today at 404-424-9105 or visit us online!