



Robinson Helicopter Parts

3948 Aviation Cir. NW, Atlanta, Georgia 30336

Phone 404.424.9105 Fax 404.601.9795



2020 Robinson R66 Special Tools Price Sheet

| Ref. | Item Part No. | Description | Price |
|------|-------------------|---|-------------|
| - | RC-MT-R66A | Complete R66 Special Tools Set (Items 1-28) and 2020 Probalancer | \$24,383 |
| - | RC-MT-R66B | Complete R66 Special Tools Set (Items 1-26, 28) w/out Probalancer | \$10,383.45 |
| - | KI-6601 | R66 Minimum Spares Kit (Supersedes KI-198) | \$14,700 |
| 1. | MT054-1 | Main Rotor Gearbox Drain Assembly - Quick Disconnect | \$197.00 |
| 2. | MT122-6 | Micrometer Assembly - Main Rotor Hub, Bolt Stretch | \$1,490.00 |
| 3. | MT146-4 | Blocks - Swashplate Rigging (set of 2) | \$171.00 |
| 4. | MT147-1 | Bleed Tool - Main Rotor Blade Spindle | \$370.00 |
| 5. | MT179-4 | Balancing Bar - Tail Rotor Assembly Static Balance | \$328.00 |
| 6. | MT260-6 | Tail Rotor Drive Shaft Runout Attachments Kit | \$230.00 |
| 7. | MT329-6 | Plug - Main Rotor Hub Bearing Installation | \$221.00 |
| 8. | MT352-1 | Main Rotor Blade Trim Tab Gage | \$448.00 |
| 9. | MT354-4 | Teeter Moment Tool (MT354-7) | \$402.00 |
| 10. | MT357-2 | 0.375-inch diameter Reamer | \$94.00 |
| 11. | MT357-3 | 0.156-inch diameter Steel Drill | \$5.00 |
| 12. | MT357-4 | Hex Driver (Snap-On Part No. FABL8) | \$44.50 |
| 13. | MT357-5 | Torque Adapter (Snap-On Part No. FRDH101) | \$52.00 |
| 14. | MT359-1 | Spring Scale (0-30 lb) | \$279.00 |
| 15. | MT384-1 | Hydraulic Test Pump (U.S / Canada / Mexico - 110-volt), OR | \$2,450.00 |
| 16. | MT384-2 | Hydraulic Test Pump (Outside North America - 220-volt) | |
| 17. | MT525-7 | Main Rotor Blade Rigging Fixture | \$198.00 |
| 18. | MT525-9 | Tail Rotor Blade Rigging | \$185.00 |
| 19. | MT526-8 | Bender Assembly - Trim Tab, Main Rotor Blade | \$512.00 |
| 20. | MT527-1 | Helicopter Lifting Fixture | \$705.00 |
| 21. | MT548-8 | Fitting (Engine Hoist Adapter) | \$185.00 |
| 22. | MT549-1 | Spacer - Spindle Boot (set of 2) | \$98.00 |
| 23. | MT549-2 | Plate - Spindle Boot | \$54.50 |
| 24. | MT556-11 | Kit Tools - Tail Rotor Hub Bearing Replacement (MT556-17) | \$660.00 |
| 25. | MT643-1 | Support Weldment - Main Rotor Hub Bearing Installation | \$517.00 |
| 26. | MT759-1 | Blocks - Cyclic Rigging | \$487.00 |
| 27. | 2020HR | ACES Probalancer Analyzer (or equivalent dynamic balancer) | \$14,000 |
| 28. | AN970-4 | Washer - Tap Test Tool | \$0.45 |