



Robinson Helicopter Parts

3948 Aviation Cir. NW, Atlanta, Georgia 30336

Phone 404.424.9105 Fax 404.601.9795



### 2022 (Q1) Rotorcorp Lycoming Engine Pricing

Rotorcorp is pleased to offer a full complement of factory Lycoming engines and field overhauled engines for your Robinson R22 or R44 Helicopter. Robinson helicopter operators and maintenance facilities around the world can now take advantage the best pricing for factory new/outright or exchange engines with our turn-key global shipping and core return program. Rotorcorp can even coordinate your engine with the appropriate Robinson buildup kit for seamless installation. Call today for specials and discounts!

### **R22 Beta: Lycoming O-320-B2C Engines**

	Current	Increased Price
<b>Lycoming Factory Overhaul Exchange (HENPL-9715)*</b> .....	<b>\$32,670</b>	<b>\$34,280</b>
<b>Lycoming Factory Rebuilt Exchange (RENPL-9715)*</b> .....	<b>\$38,158</b>	<b>\$40,280</b>
<b>Lycoming Factory New Exchange (ENPL-9715)*</b> .....	<b>\$61,843</b>	<b>\$63,335</b>
<b>Lycoming Factory New Outright (ENPL-9715)</b> .....	<b>\$77,843</b>	<b>\$79,385</b>
<b>Robinson Factory Overhaul Exchange (A009-8R)**</b> .....	<b>\$33,000</b>	<b>n/a</b>
<b>Field Direct Overhauled (Your Engine)</b> .....	<b>\$23,440</b>	<b>n/a</b>
<b>Engine Build-Up Kit KI-2204</b> .....	<b>\$2,800</b>	<b>n/a</b>

\*Lycoming Factory exchange O-320 engines require either a \$16,000 core deposit with order or submittal of a core engine in advance of the order to waive core deposit. Note: Per Lycoming SL-277, as of Jan. 6, 2020 Lycoming factory engines will no longer include an Alternator or Starter. \*\* Robinson Factory exchange engines includes starter, alternator and are "built-up" with KI-2204 included, require \$15,000 core deposit (R5845) or submittal of core engine in advance of order to waive core deposit. Prices do not include freight and shipping charges. Prices are subject to change without notice.

### **R22 Beta II: Lycoming O-360-J2A Engines**

	Current	Increased Price
<b>Lycoming Factory Overhaul Exchange (HENPL- RT10603)*</b> .....	<b>\$27,870</b>	<b>\$29,224</b>
<b>Lycoming Factory Rebuilt Exchange (RENPL- RT10603)*</b> .....	<b>\$33,358</b>	<b>\$35,223</b>
<b>Lycoming Factory New Exchange (ENPL-RT10603)*</b> .....	<b>\$61,536</b>	<b>\$63,022</b>
<b>Lycoming Factory New Outright (ENPL- RT10603)</b> .....	<b>\$77,936</b>	<b>\$79,422</b>
<b>Robinson Factory Overhaul Exchange (A009-11R)**</b> .....	<b>\$34,000</b>	<b>n/a</b>
<b>Field Direct Overhauled (Your Engine)</b> .....	<b>\$23,350</b>	<b>n/a</b>
<b>Engine Build-Up Kit KI-2205</b> .....	<b>\$3,400</b>	<b>n/a</b>

\*Lycoming Factory exchange engines require either a \$16,400 core deposit with order or submittal of core engine in advance of the order to waive core deposit. Note: Per Lycoming SL-277, as of Jan. 6, 2020 Lycoming factory engines will no longer include an Alternator or Starter \*\* Robinson Factory exchange engines includes starter, alternator and are "built-up" with KI-2205 included, require \$16,400 core deposit (R8087) or submittal of core engine in advance of order to waive core deposit. Prices do not include freight and shipping charges. Prices are subject to change without notice.



Robinson Helicopter Parts

3948 Aviation Cir. NW, Atlanta, Georgia 30336

Phone 404.424.9105 Fax 404.601.9795

## R44 Raven I: Lycoming O-540-F1B5 Engines

	Current	Increased Price
Lycoming Factory Overhaul Exchange (HENPL-RT10877)* .....	\$42,205	\$44,140
Lycoming Factory Rebuilt Exchange (RENPL- RT10877)* .....	\$48,303	\$51,040
Lycoming Factory New Exchange (ENPL- RT10877)* .....	\$82,269	\$84,154
Lycoming Factory New Outright (ENPL- RT10877).....	\$102,670	\$104,554
Robinson Factory Overhaul Exchange (C009-13R)** .....	\$45,000	n/a
Field Direct Overhaul (Your Engine) .....	\$33, 120	n/a
O-540 Engine Build-Up Kit KI-4405 .....	\$5,300	n/a

\*Exchange engines require either a \$20,400 core deposit with order or submittal of core engine in advance of order to waive core deposit. Note: Per Lycoming SL-277, as of Jan. 6, 2020 Lycoming factory engines will no longer include an Alternator or Starter \*\* Engine includes starter, alternator and is "built-up" with KI-4405. Prices do not include freight and shipping charges. Prices are subject to change without notice.

## R44 Raven II: Lycoming IO-540-AE1A5 Engines

	Current	Increased Price
Lycoming Factory Overhaul Exchange (HENPL-RT10586)* .....	\$50,847	\$53,116
Lycoming Factory Rebuilt Exchange (RENPL- RT10586)* .....	\$56,944	\$60,126
Lycoming Factory New Exchange (ENPL- RT10586)* .....	\$106,391	\$108,741
Lycoming Factory New Outright (ENPL- RT10586).....	\$127,991	\$130,341
Robinson Factory Overhaul Exchange (D009-4R)** .....	\$57,000	n/a
Direct Field Overhaul (Your Engine).....	\$44,200	n/a
IO-540 Engine Build-Up Kit KI-4406 .....	\$4,900	n/a

\*Exchange engines require either a \$21,600 core deposit with order or submittal of core engine in advance of order to waive core deposit. Note: Per Lycoming SL-277, as of Jan. 6, 2020 Lycoming factory engines will no longer include an Alternator or Starter. \*\* Engine includes starter, alternator and is "built up" with KI-4405. Prices do not include freight and shipping charges. Prices are subject to change without notice.

**Call Rotorcorp today 404-424-9105 or visit us online!**